



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: December 9, 2008

Reviewed: LR

Mine Name: Henefer Stockpiles	Permit Number: S/043/0011
Operator Name: Interstate Brick Company	Inspection Date: 12/04/2008
Inspector(s): Brett Gregory for Leslie Heppler <u>L</u>	Time: 12:00 PM
Other Participants: None	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$18,600

Permit fee: Current.

Purpose of Inspection: This was a routine annual inspection of the site.

Inspection Summary: Photos are attached.

2) The bike jumps present a safety hazard and the operator should evaluate their liability.

6) The previous inspection of this site had documented that the clay stockpile was from the landfill expansion by the county. It appears no more material has been added to this existing stockpile. Large amounts of Russian thistle have grown and only a small amount of clay has been removed on the east side (see photographs). Operator should consider controlling invasive weeds to help assure successful final revegetation efforts.

Conclusions and Recommendations: Recommended that the operator post appropriate no trespassing signs to keep public out of the permitted area. DOGM will continue to monitor this site.

Inspector's Signature

BG:vs

cc: John Hewitt

O:\M043-Summit\M0430011-HeneferStockpiles\inspections\insp-12042008.doc



Stockpile highwall.



Russian thistle.



Rain runoff into the field – Operator to evaluate and remediate.



Berm has been breached.



Garbage to be removed.



Bike jumps that can be a safety hazard



Southern berm.



View of the top of the stockpile.